



TARA PAINTS & CHEMICALS

(An ISO 9001:2015 Certified Company)

A - 423 / 14, Mahagujarat Industrial Estate, Sarkhej - Bavla Road, Lane Behind Satyam Arcade,
Village : Moraiya, Ahmedabad - 382 210, Gujarat (India)

Tel: (F): +91 8000011774, E-mail: taralac@hotmail.com , taralac@taralac.com Website: www.taralac.com

EPOXY FLOOR COATING SOLVENT BASED

General Description:

EPOXY TOP COAT PAINT is a, two components, and high build epoxy coating, Hardener and selected silica aggregates for a highest mechanical performance and resistance to chemical attack. system consisting of an epoxy resin and polyamide or alkamine hardener that gives a glossy finish. Specially formulated to give superior adhesion, abrasion resistant and excellent heavy-duty coating.

Major Uses:

Ideal for machine shops, heavy engineering plants, chemical process areas, passenger walkways in airports when an attractive appearance must be coupled with exceptional wear resistance and laboratories subjected to mild acids and spillages. It is also widely used for commercial and industrial establishments, heavy-duty loading bays and storage. On floors such as breweries, textile mills, distilleries and other food processing and manufacturing industries.

Advantages:	
<ul style="list-style-type: none"> • High chemical resistance. • Hard wearing. • Easy to clean – seamless. • Flexible and waterproof. 	<ul style="list-style-type: none"> • Available in wide range of color. • Exceptional wear – resistance. • Non – slip also Available • Excellent abrasion resistant.

Characteristics and Physical Properties		Chemical Resistance Properties	
Appearance	Coloured Liquid	Hydrochloric Acid -	Excellent
Mixing Ratio	3 : 1	Sulphuric Acid,20% -	Excellent.
Solid Content	50% - 75% depending on shade.	Phosphoric Acid, 20% -	Excellent.
Specific Gravity	1.2 – 1.9	Lactic Acid, 20% -	Very Good.
Pot Life @ 30°C.	45 – 60 minutes.	Sodium hydroxide,50% -	Excellent.
Initial Hardness @30°C	8 - 10 Hours.	Water, de – ionized -	Unaffected
Full Cure @30°C	7 Days	Sulfuric Acid, 14% -	Unaffected
Compressive Strength	60 N/mm ²	Nitric Acid, 10% -	Unaffected
Flexural Strength	20 N/mm ²	Acetic Acid, 30% -	Unaffected
Water Absorption	0.2%	Caustic Soda, 20% -	Excellent
Modulus of Elasticity	5500 N/mm ²	Petrol -	Unaffected
		Toluene -	Stiffened
		Xylene -	Unaffected
		Styrene -	Unaffected
		Hydraulic Fluid -	Unaffected
		Alcohol -	Excellent.
		Ketones -	Good.

All the information given here are as per the results obtained in laboratory & are given in good faith to guide the user but without any warranty, the actual application results might vary depending on the conditions. We are not responsible for any loss, injury or damage resulting from the use of this information



TARALAC®

TARA PAINTS & CHEMICALS

(An ISO 9001:2015 Certified Company)

A - 423 / 14, Mahagujarat Industrial Estate, Sarkhej - Bavla Road, Lane Behind Satyam Arcade,
Village : Moraiya, Ahmedabad - 382 210, Gujarat (India)

Tel: (F): +91 8000011774, E-mail: taralac@hotmail.com , taralac@taralac.com Website: www.taralac.com

Surface Preparation:

Old Concrete:

Concrete should be dry, free from dust, oil, loose debris and other contaminants. Remove all existing coat (if any) by scraping, grinding or with paint remover. Apply one (1) coat of multi – etch solution and rinse with fresh water and let it dry for 24 hrs. to ensure an excellent penetration.

New Concrete:

New concrete should be cured for at least 28 days, the moisture content of the substrate should be less than 5%. Apply one (1) coat of etch solution, rinse and let it dry. Remove all loose debris prior to the application of EPOXY TOP COAT PAINT.

Maintenance:

Remove all traces of oil, grease and other contaminants with suitable degreaser and detergent. Remove all rust and loose materials by power tool cleaning or by wire brushing. Application of wash primer to damaged or rusted surface is recommended prior to the application of EPOXY TOP COAT PAINT. Surface contaminated with oil or grease should be flame cleaned or by using a degreaser and wash with detergent.

Priming:

Apply 1 – 2 coat of Epoxy Base Coat as a sealer and conditioner. Primer should be tack – free prior to application of EPOXY TOP COAT PAINT.

Storage:

At least 1 year in unopened cans. The product should be stored in cool and dry area. Keep container tightly closed.

Cleaning of Tools:

All tools should be cleaned with Wash Thinner or TARALAC Epoxy Thinner as soon as possible.

Physiological Hazards:

Keep Resin and Hardener away from eyes and skin contact. Good ventilation should be provided particularly in closed work areas. Keep uncured epoxy materials away from the mouth, food or drink, do not use empty tins to store food and do not empty cans into drains. Always wear gloves and safety materials when handling this product. Clean any splashes or smears from the skin immediately, using warm water and soap. Avoid inhaling vapor.