



# TARA PAINTS & CHEMICALS

(An ISO 9001:2015 Certified Company)

A - 423 / 14, Mahagujarat Industrial Estate, Sarkhej - Bavla Road, Lane Behind Satyam Arcade,  
Village : Moraiya, Ahmedabad - 382 210, Gujarat (India)

Tel: (F): +91 8000011774, E-mail: taralac@hotmail.com , taralac@taralac.com, Website: www.taralac.com

## NC PS Grey/White/Black

### Introduction

Function of primer surfacer grey is to even out all minor surface defects, still left on the primered and puttied surface of a vehicle. It has ideal balance between the binder and the pigment/extenders so that it can achieve evenness on a surface and also can offer a non-absorbent finish so that subsequent coat of a finishing paint does not penetrate its film, thereby loosing gloss. The above primers contain no added lead or chromate.

Physicals constants	
Color	Pleasing Grey
Finish	Smooth & Silky.
Wt. per Lt	Nearly 1.21 Kgs
Viscosity at 30°C	25 Sec by ford cup No.4 when thinned with Butyl Acetate 1:1 by volume
Flexibility	Passed 3 mm bending on bending mandrel
Sanding	Can be easily rubbed down to yield smooth & silky surface
Thinner	Taralac Solvent Mix 555\211\111

### Surface Preparation

- The metal or wood surface to be coated should be free from dirt, rust, flakes, oil, grease or other loose particles.
- If previously coated, remove the coating by sanding.
- Apply Taralite Red Oxide or Auto Oil Primer Brown.
- Sand the surface with emery paper no. 180.
- Followed by smooth sanding with emery paper no. 320 or 400 and cleaning of the surface to remove dust.
- Apply Taralac NC Putty Grey with Putty knife or by thinning and applying with brush.
- Smooth sand the surface with emery paper no. 180 followed by emery paper no 320 or 400 and cleaning of the surface to remove loose dust.
- Apply Taralac NC PS Grey with brush or spray to remove the minor defects on the surface.

### Precautions

Avoid Skin contact. Contains volatile organic solvents.

### Safety Information

Fire Hazard Class	Flammable
Safety Precaution	Wear Protective clothing like overalls, gloves and goggles
Storage	Store in a cool and dry place
Disposal	Dispose in land filling. Do not dispose in any drain or water channel.

(Covering capacity is indicated on the results obtained on normal prepared surfaces. This information is given in good faith but without warranty.)